



1. Supplier Information		2. Product Change/ Recall Notice No.	2a. Include on www.ofsoptics.com	
OFS FITEL LLC, One BrightWave Boulevard, Card Contact Engineer: Tom Liang vliang@ofsoptics.com	rollton, GA 30117	2012-0003-1 D	Yes	
3. Issue Date of Change/Recall	4. System & Product Description			
12-27-2011	Replacement	Replacement parts for S199S fusion splicers		
5. New Product ID n/a	6. Old Product ID			
7. Associated Products or Changes Affected Service and repair for S199S splicers will be av	railable only until stoc	ck of parts is exhausted		
8. Drawing No.	9. Product Change Classification			
n/a	Class D			
10. Classification Substantiation n/a				
11. Reason(s) for Change/Recall				
Product at end of life cycle				
12. Description of Change/Recall Replacement parts for S199S are discontinued a	as of December 2011			
13. Effect of Change/Recall N/A				
14. Material\Product Affected				
S199S fusion splicer and associated parts for th	is model			
15. Documentation Affected none				
16. Supplier Implementation Date 12/31/2011	. Modification Com	pletion Date		
18. Modification/Recall Location				
N/A				
19. Modification/Recall Cost				
N/A				
20. Location and Quantity of Equipment N/A				
21. Attachments				
None				
22. Comments				